Oil Field Environmental Incident Summary

Responsible Party: Continental Resources, Inc.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: Beulah CTB

Field Name: Well File #: 0

Date Incident: 1/29/2014 Time Incident: 05:00 Facility ID Number:

County: BOWMAN Twp: 129 Rng: 104 Sec: 4 Qtr: NW NW

Location Description: misted off location, approx. 100 yds x 100 yds

Submitted By: Stacy Aguirre Received By:

Contact Person: Stacy Aguirre

PO BOX 269000

Oklahoma City, OK 73126

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Spilled Units Recovered Units Followup Units

	Opiniou		710007070	• • • • • • • • • • • • • • • • • • • •
Oil	0.3	barrels	0	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

approx. 100 yds x 100 yds

Potential Environmental Impacts:

pasture soil

Action Taken or Planned:

landowner was contacted upon discovery of the misted area off location; the ground is frozen, evaluating clean-up options and will coordinate with the landowner

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 2/6/2014 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 2/13/2014 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spoke with the production supervisor for Continental while on site for the Della CTB inspection on 2/4/14. The production supervisor informed me that there had been a glitch when he tried to enter this site's information into our incident data base, which led to the information not being entered within the 24-hour timeframe. He informed me that he had spoken to the landowner and they were fine with the cleanup and would like to take a look at it in the spring. Follow up with inspection when in the area.

Date: 10/7/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location on 10/7/2014.

No sign of spill in the described location. However, there is a small burn mark next to the CTB location just to the east of the flare pit.

No followup is necessary.

Date: 3/10/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 10, 2016.